



Dedicated Kit TF2351

Fits the following vehicles

Audi A4 All 2009 -

Audi A4 March 2008-March 2009

Audi A5 All 2009 -

Audi A8 2008-2010

Audi Avant 2005-

Audi Q5 SUV 2009 -

Audi Q7 2006+

BMW 1 Series All 2005 -

BMW 3 Series All 2005 -

BMW 3 Series All 2005 -

BMW 5 Series All 2003 -

BMW 5 Series F10, F11 Tourer Estate 2010 -

BMW X1 SUV 2009-

BMW X5 4WD Apr 2007 -

BMW X6 4WD 2010 -

Ford C Max 2011-

Ford Focus 2011-

Landrover Freelander II 4WD 2007 -

Mercedes C Class (203) Saloon 2001-

Mercedes C Classe (204) All 2007-

Mercedes E Class (W212) All 2010 -

Mercedes ML (W169) / ML320Sport/R Class/ GLClass 4WD 2005 -

Mitsubishi Outlander

Alpha-numeric codes refer to the vehicle map on the front page					
Vehicle	SocketCable Entry Point	PowerSource	FuseBattery	CAN Module/Dedicated Kit	Can HI LO location
Audi A4 All 2009 -	M60 Grommet	Fusebox	JR45	TF2302, TF2351	JR45 Control centre
Audi A4 March 2008-March 2009	See note below			TF2302, TF2351	
Audi A5 All 2009 -	M60 Grommet	Fusebox	JR45	TF2302, TF2351	JR45 Control centre
Audi A8 2008-2010	N62 Grommet	Fusebox	JR45	TF2302, TF2351	JR45/113
Audi Avant 2005-	M60 Grommet	Fusebox	JR45	TF2302, TF2351	JR45 Control centre
Audi Q5 SUV 2009 -	M60 Grommet	Fusebox	JR45	TF2302, TF2351	JR45 Control centre
Audi Q7 2006+	I49 Grommet	Fusebox	JR45	TF2302, TF2351	JR45 Control centre
BMW 1 Series All 2005 -	M60	Powerpoint at M59	JR45	TF2302, TF2351	JR47 Twisted pair
BMW 3 Series All 2005 -	M60	Fusebox.	JR45	TF2302, TF2351	JR47 Twisted pair
BMW 3 Series All 2005 -	M60	Fusebox.	JR45	TF2302, TF2351	JR47 Twisted pair
BMW 5 Series All 2003 -	M60	JR47	I40 or I39	TF2302, TF2351	JR47 Twisted pair
BMW 5 Series F10, F11 Tourer Estate 2010 -	M60 Grommet	Battery	I39	TF2302, TF2351	B9 above brake pedal, twisted pair to blue plug
BMW X1 SUV 2009-	M60	Powerpoint at M59	JR45	TF2302, TF2351	JR47 Twisted pair
BMW X5 4WD Apr 2007 -	M60	Fusebox.	JR45	TF2302, TF2351	JR45 twisted pair
BMW X6 4WD 2010 -	M60 Grommet	Fusebox.	JR45	TF2302, TF2351	JR47 Twisted pair

Alpha-numeric codes refer to the vehicle map on the front page				
HI LO colours/pins	Hard Brake location	Is data 2way?	For Recode info see:	RecodeAdds
HI Orange/green, LO Orange/brown	JR45 Control panel	Yes	VCDS Coding Guide for VAG vehicles	RECODE ADDS: C2 on dash; PDC; TSP; Auto hold brake adjustment
			N/A	Warning: Audi A4 and A5, vehicles built March-April 2008 to March-April 2009 . Most models need extensive modification to their cooling systems and, possibly a new alternator to accommodate towing. Vehicles built April 2009 and after are OK
HI Orange/green, LO Orange/brown	JR45 Control panel	Yes	VCDS Coding Guide for VAG vehicles	RECODE ADDS: C2 on dash; PDC; TSP; Auto hold brake adjustment
HI Orange/Green, LO Orange/Brown	-	Yes	VCDS Coding Guide for VAG vehicles	RECODE ADDS: C2 on dash; PDC; TSP; Auto hold brake adjustment
HI Orange/green, LO Orange/brown	JR45 Control panel	Yes	VCDS Coding Guide for VAG vehicles	RECODE ADDS: C2 on dash; PDC; TSP; Auto hold brake adjustment
HI Orange/green, LO Orange/brown	JR45 Control panel	Yes	VCDS Coding Guide for VAG vehicles	RECODE ADDS: C2 on dash; PDC; TSP; Auto hold brake adjustment
HI Orange/Green. LO Orange/brown	JR45 Control centre	Yes	VCDS Coding Guide for VAG vehicles	RECODE ADDS: C2 on dash; PDC; TSP; Auto hold brake adjustment
HI Orange/green, LO Green	N/A	Yes	N/A	Functions added automatically: C2 on dash; PDC; FCO
HI Orange/green, LO Green	N/A	Yes	N/A	Functions added automatically: C2 on dash; PDC; FCO.
HI Orange/ green, LO Green	N/A	Yes	N/A	Functions added automatically: C2 on dash; PDC; FCO.
HI Black, LO Yellow		Yes	N/A	
HI Orange/green, LO Green		Yes	N/A	C2, PDC and Fog cut out are activated automatically
HI Orange/green, LO Green	N/A	Yes	N/A	Functions added automatically: C2 on dash; PDC; FCO
HI Orange/green, LO Green	JR45 Black/yellow	Yes	N/A	CAN also at B9. Functions added automatically: C2 on dash; PDC; FCO. Very early models: if, with CAN module fitted, air conditioning only blows cold when trailer is connected, this is caused by a BMW software error. BMW will update coding.
HI Orange/green, LO Green	N/A	Yes	N/A	Automatically enabled: C2 on dash; Switches off PDC but not Foglight

Alpha-numeric codes refer to the vehicle map on the front page					
Vehicle	SocketCable Entry Point	PowerSource	FuseBattery	CAN Module/Dedicated Kit	Can HI LO location
Ford C Max 2011-	I38 Grommett	Fusebox	JL43	TF2302, TF2351	JL43 Green plug
Ford Focus 2011-	I38 Grommett	Fusebox	JL43	TF2302, TF2351	JL43 Green plug
Landrover Freelander II 4WD 2007 -	I38 Grommet	Fusebox	I35/JL42	TF2302, TF2351	I35/38 on Multiplug
Mercedes C Class (203) Saloon 2001-	M59/60 Grommet	Fusebox	JL42	TF2302, TF2351	JL42 Twisted pair
Mercedes C Classe (204) All 2007-	M59/60 Grommet	Fusebox.	JR47	TF2302, TF2351	JR48
Mercedes E Class (W212) All 2010 -	M60 Grommet	Fusebox.	JR47	TF2302, TF2351	JR46/47 Twisted pair
Mercedes ML (W169) / ML320Sport/R Class/GLClass 4WD 2005 -	M60	Fusebox.	JR45	TF2302, TF2351	JR45 twisted pair
Mitsubishi Outlander	JR46	Fusebox	A4	TF2302, TF2351	OBDII

Alpha-numeric codes refer to the vehicle map on the front page				
HI LO colours/pins	Hard Brake location	Is data 2way?	For Recode info see:	RecodeAdds
HI Grey/Orange, LO Violet/Orange	-	Yes	-	Recoding adds C2 on dash; PDC; FCO
HI Grey/Orange, LO Violet/Orange		Yes	-	Recoding adds C2 on dash; PDC; FCO
Grey/orange, Purple/orange	JL42 Purple/brown wire	Yes	Recoding data for non-VAG vehicles	Recoding adds C2 on dash; PDC
HI Brown/red, LO Brown		Yes	Recoding data for non-VAG vehicles	Functions added automatically: FCO
HI Brown/red, LO Brown	JR46	Yes	N/A	If a SAM-low is installed in the rear of the vehicle, it needs to be exchanged for a higher-quality, trailer compatible SAM. Purchase from Daimler automotive supply stores. If PDC cuts out, moving the car will reset it. Functions added automatically: FCO, PDC cut off, C2 on dash
HI Brown/red, LO Brown		Yes	N/A	If a SAM-low is installed in the rear of the vehicle, it needs to be exchanged for a higher-quality, trailer compatible SAM. Purchase from Daimler automotive supply stores. Functions added automatically: C2 on dash; PDC; FCO
HI Brown/red, LO Brown	JR46 Black/red	Yes	Recoding data for non-VAG vehicles	Recoding adds Park assist cut off R Class: Large 13mm power terminal is close to chassis. If shorted, blows midi fuse by battery under driver's seat. Fuse also controls seat movement.
Pins 6/14	-	No	N/A	Module reads CAN only, to operate lights and 12S. Is not 2-way